

**Work Order ID 98032**

Tuesday, March 05, 2013 1:36:34 PM

**\*98032\***

Page 1

Item ID: D2221

Accept

**\*N900040100\***

Setup

Start

**\*NS1\***

Revision ID:

Item Name: 350 Basket Base

Stop

**\*NS2\***

Start Date: 3/4/2013 Start Qty: 1.00

**\*1\***

Cust Item ID:

Required Date: 4/9/2013 Req'd Qty: 1.00

**\*1\***

Customer:

Reference:

Approvals: Process Plan:

*8*Date: *B-03-5*

Tooling:

Date:

Run

Start

**\*NR1\***

QC:

Date:

SPC (Y/N):

Date:

Stop

**\*NR2\***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

D2221	Rev H
-------	-------

100	0.00
-----	------

<b>*100*</b>	Large Fab
--------------	-----------

Large Fab	Memo
-----------	------

Large Fab	0.00
	1- assemble all ribs and both D2581 in DT9444 jig, weld as per dwg D2221
	2- remove basket from jig and weld D3442-1 shims and D2232-3 hinges as per dwg D2221
	3- tack weld mesh on basket as per dwg D2221
	A/R ER316 S.S. Rod Batch: <i>11022357</i>

*8/11 13-3-26*

\*\*\*PLEASE NOTE SEE DWG\*\*\*

IF MAKING -141-041A CUT BUSHING ON BASE BOTH ENDS, OR -143/-043A CUT BUSHING ON ONE SIDE ONLY OF BASKET BASE AS PER DWG

110	QC9- Inspect visual per QSI004- Fusion Welds	0.00
-----	--	------

<b>*110*</b>	Memo	0.00
--------------	------	------

QC		
----	--	--

Quality Control		
-----------------	--	--

*B-03-27*

*DAS  
09  
2013*

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order:		DISPOSITION			AGAINST DEPARTMENT/PROCESS							
Part No. _____		Rework	Scrap	Use-as-is	Skid-tube	Machining	Crosstube	Water Jet	Engineering			
NCR No. _____		Work Order Update			Thermoforming	Large Fab	Small Fab	Prod. Eng. Coor.	Quality			
							Finishing	Rec/Store/Packaging	Other			
							Composite	Supplier				
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification	QC Inspector	
Doc/Data												
Equip/Tooling												
Operator												
Material												
Setup												
Other												
Process												
Supplier												
Training												
Unapproved												
FAULT CATEGORY												
Landing Gear	General											
	Bending	Bend	Grain	Ovalized	Pressure/Forced							
	Centre Not Concentric to O/S	BOM/Route	Hardware	Over/Under tolerance	Temperature/Cure							
	Cracks	Broken/Damaged	Inspection Incomplete	Part Incorrect	Weld							
	Crushed/Crimped.	Burrs	Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled							
	Cuffs	Contamination	Maintenance	Part Moved								
	Heat Treat	Countersink	Mislabeled	Positioned Wrong								
	Inspection Strip in Tube	Cut Too Short	Misread	Power Loss/Surge	Other							
	Ripples in Bend	Drill Holes	Offset									
	Torque Waves in Extrusion	Drawing	Out of Calibration									
	Turning Sequence	Finish	Out of Sequence									
	Wave/Twist in Tube	Folio	Outside Dimensions									

**Work Order ID 98032**

Tuesday, March 05, 2013 1:36:34 PM

**\*98032\***

Page 2

Item ID: D2221

Accept

**\*N900040100\***

Setup Start

**\*NS1\***

Revision ID:

Item Name: 350 Basket Base

Stop

**\*NS2\***

Start Date: 3/4/2013 Start Qty: 1.00

**\*1\***

Cust Item ID:

Required Date: 4/9/2013 Req'd Qty: 1.00

**\*1\***

Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start

**\*NR1\***

QC:

Date:

SPC (Y/N):

Date:

Stop

**\*NR2\***Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

120

QC6- Inspect dimensions to drawing

0.00

**\*120\***

QC

Quality Control

B-03-27

DAS  
09  
89

125

Pressure Wash per QSI005 4.3

0.00

**\*125\***

HandFinish

Hand Finishing

Memo

0.00

1 26/13-3-27

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear	General										
	Bending <input type="checkbox"/>	Bend <input type="checkbox"/>	Grain <input type="checkbox"/>			Ovalized <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>				
	Centre Not Concentric to O/S <input type="checkbox"/>	BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>			Over/Under tolerance <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>				
	Cracks <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>			Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>				
	Crushed/Crimped <input type="checkbox"/>	Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>			Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>				
	Cuffs <input type="checkbox"/>	Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>			Part Moved <input type="checkbox"/>					
	Heat Treat <input type="checkbox"/>	Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>			Positioned Wrong <input type="checkbox"/>					
	Inspection Strip in Tube <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>			Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>				
	Ripples in Bend <input type="checkbox"/>	Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>								
	Torque Waves in Extrusion <input type="checkbox"/>	Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>								
	Turning Sequence <input type="checkbox"/>	Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>								
	Wave/Twist in Tube <input type="checkbox"/>	Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>								

Work Order ID 98032

Tuesday, March 05, 2013 1:36:34 PM

\*98032\*

Page 3

Item ID: D2221

Accept

\*N900040100\*

Setup

Start \*NS1\*

Revision ID:

Item Name: 350 Basket Base

Stop

\*NS2\*

Start Date: 3/4/2013 Start Qty: 1.00

\*1\*

Cust Item ID:

Required Date: 4/9/2013 Req'd Qty: 1.00

\*1\*

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start

\*NR1\*

QC:

Date:

SPC (Y/N):

Date:

Stop

\*NR2\*

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

130

\*130\*

Powdercoat

Powder Coating

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

0.00

1X0 MF 13/03/27

Memo

0.00

1- Plug holes prior to

1ST COAT:

10:50

START TIME:

400°F

OVEN TEMPERATURE:

FINISH TIME:

\*\*\*\*\* 2nd coat if necessary\*\*\*\*\*

2ND COAT:

START TIME:

OVEN TEMPERATURE:

FINISH TIME:

140

\*140\*

QC

Quality Control

QC3- Inspect Part Finish

0.00

Memo

0.00

1 13-3-D7

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS																												
			Rework <input type="checkbox"/>	Scrap <input type="checkbox"/>	Use-as-is <input type="checkbox"/>	Work Order Update <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Machining <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Finishing <input type="checkbox"/>	Composite <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Supplier <input type="checkbox"/>	Engineering <input type="checkbox"/>	Quality <input type="checkbox"/>	Other <input type="checkbox"/>													
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description			Sign & Date	Verification		QC Inspector																					
Doc/Data <input type="checkbox"/>																																		
Equip/Tooling <input type="checkbox"/>																																		
Operator <input type="checkbox"/>																																		
Material <input type="checkbox"/>																																		
Setup <input type="checkbox"/>																																		
Other <input type="checkbox"/>																																		
Process <input type="checkbox"/>																																		
Supplier <input type="checkbox"/>																																		
Training <input type="checkbox"/>																																		
Unapproved <input type="checkbox"/>																																		
FAULT CATEGORY																																		
Landing Gear <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped. <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube <input type="checkbox"/>	General																																	
	Bend <input type="checkbox"/>	BOM/Route <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>	Burrs <input type="checkbox"/>	Contamination <input type="checkbox"/>	Countersink <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>	Drill Holes <input type="checkbox"/>	Drawing <input type="checkbox"/>	Finish <input type="checkbox"/>	Folio <input type="checkbox"/>	Grain <input type="checkbox"/>	Hardware <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Misread <input type="checkbox"/>	Offset <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Part Moved <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>	Weld <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>	Other <input type="checkbox"/>

Work Order ID 98032

\*98032\*

Page 4

Tuesday, March 05, 2013 1:36:34 PM

Item ID: D2221 Accept \*N900040100\* Setup Start \*NS1\*  
Revision ID:  
Item Name: 350 Basket Base Stop \*NS2\*  
Start Date: 3/4/2013 Start Qty: 1.00 \*1\* Cust Item ID:  
Required Date: 4/9/2013 Req'd Qty: 1.00 \*1\* Customer:  
Reference:

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_ Run Start \*NR1\*  
QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_ Stop \*NR2\*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

150 Identify as per dwg & Stock Location: D350-6007041 98080  
\*150\* 1 1/4 13-327  
Packaging Memo 0.00  
Packaging

160 QC21- Final Inspection - Work Order Release 0.00  
\*160\* 1/4 13-04-02  
QC Memo 0.00  
Quality Control

1/4 13-04-02

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification	QC Inspector
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear	General										
	Bending <input type="checkbox"/>	Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>						
	Centre Not Concentric to O/S <input type="checkbox"/>	BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>						
	Cracks <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>						
	Crushed/Crimped. <input type="checkbox"/>	Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>						
	Cuffs <input type="checkbox"/>	Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>							
	Heat Treat <input type="checkbox"/>	Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>							
	Inspection Strip in Tube <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>						
	Ripples in Bend <input type="checkbox"/>	Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>								
	Torque Waves in Extrusion <input type="checkbox"/>	Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>								
	Turning Sequence <input type="checkbox"/>	Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>								
	Wave/Twist in Tube <input type="checkbox"/>	Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>								

## Picklist Print

*Tuesday, March 05, 2013 1:36:40 PM*

Page 1

Work Order ID: 98032

\*98032\*

**Parent Item:** D2221

\*D2221\*

**Parent Item Name:** 350 Basket Base

**Start Date:** 3/4/2013

**Required Date:** 4/9/2013

**Comments:** IPP Rev:J 05.09.02 Added D3442-1 KJ/JLM  
IPP Rev:K 08-08-29 revG as per dwg DD verified by:EC  
IPP Rev:L 08-09-24 plug holes prior to powder coat DD verified by:EC  
IPP Rev:M 08-12-02 revH as per dwg DD verified by:EC IPP Rev:N  
10.06.29 added pressure wash DD verf:EC

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
Part No. _____			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
NCR No. _____			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear	Bending			General							
	Centre Not Concentric to O/S			Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced				
	Cracks			BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Temperature/Cure				
	Crushed/Crimped			Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>				
	Cuffs			Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>				
	Heat Treat			Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>					
	Inspection Strip in Tube			Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>					
	Ripples in Bend			Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>				
	Torque Waves in Extrusion			Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>						
	Turning Sequence			Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>						
	Wave/Twist in Tube			Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>						
				Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>						

# Picklist Print

Page 2

Tuesday, March 05, 2013 1:36:40 PM

Work Order ID: 98032

**\*98032\***

Parent Item: D2221

**\*D2221\***

Parent Item Name: 350 Basket Base

Start Date: 3/4/2013

Required Date: 4/9/2013

Start Qty: 1.00

Required Qty: 1.00

D2232-3

Manufactured No

100

Each

16.0000

2

2

\*\*

*B 89358 -> Jx*

**\*D2232-3\***

Basket Hinge

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	16	
75581	2	
89358	14	

*13.03.20*

D2235-1

Manufactured No

100

Each

13.0000

2

2

\*\*

*B 94811 -> Jx*

**\*D2235-1\***

Basket Rib

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	13	
66895	4	
85602	4	
86051	1	
88209	4	

*13.03.20*

D2581

Manufactured No

100

Each

48.0000

2

2

\*\*

*B 94204 -> Jx*

**\*D2581\***

Mounting Bracket

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	48	
70766	2	
81253	1	
82506	2	
83230	3	
85452	2	
87706	2	
92871	10	
94204	26	

*13.03.20*

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS														
			Rework <input type="checkbox"/>	Scrap <input type="checkbox"/>	Use-as-is <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Machining <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Finishing <input type="checkbox"/>	Composite <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Supplier <input type="checkbox"/>	Engineering <input type="checkbox"/>	Quality <input type="checkbox"/>	Other <input type="checkbox"/>
Part No. _____			Work Order Update <input type="checkbox"/>																	
NCR No. _____																				
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance			Initial Chief Eng	Action Description			Sign & Date	Verification			QC Inspector					
Doc/Data																				
Equip/Tooling																				
Operator																				
Material																				
Setup																				
Other																				
Process																				
Supplier																				
Training																				
Unapproved																				
FAULT CATEGORY																				
Landing Gear	General																			
	Bending <input type="checkbox"/>	Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced Temperature/Cure															
	Centre Not Concentric to O/S <input type="checkbox"/>	BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Weld <input type="checkbox"/>															
	Cracks <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>															
	Crushed/Crimped. <input type="checkbox"/>	Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>																
	Cuffs <input type="checkbox"/>	Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>																
	Heat Treat <input type="checkbox"/>	Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>																
	Inspection Strip in Tube <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>																
	Ripples in Bend <input type="checkbox"/>	Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>	Other <input type="checkbox"/>																
	Torque Waves in Extrusion <input type="checkbox"/>	Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>																	
	Turning Sequence <input type="checkbox"/>	Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>																	
	Wave/Twist in Tube <input type="checkbox"/>	Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>																	

# Picklist Print

Page 3

Tuesday, March 05, 2013 1:36:40 PM

Work Order ID: 98032

**\*98032\***

Parent Item: D2221

**\*D2221\***

Parent Item Name: 350 Basket Base

Start Date: 3/4/2013

Required Date: 4/9/2013

Start Qty: 1.00

Required Qty: 1.00

D3442-1

Manufactured No

100

Each

16.0000

2

2

\*\*

*B86720 → 2x*

**\*D3442-1\***

Shim

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	16	
86720	12	
90017	4	

*14/3/03/20*

D3825-041

Manufactured No

100

Each

16.0000

2

2

\*\*

*B89380 → 2x*

**\*D3825-041\***

Rib Assembly (Basket End)

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	16	
89380	12	
89450	4	

*14/3/03/20*

D3826-041

Manufactured No

100

Each

10.0000

2

2

\*\*

*B82306 → 2x*

**\*D3826-041\***

Rib / Gusset Assembly

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA004	4	
90838	4	
WA007	6	
90722	6	

*14/3/03/20*

D3827-041

Manufactured No

100

Each

8.0000

1

1

\*\*

*B90866 14/3/03/20*

**\*D3827-041\***

Rib Assembly (Inboard)

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
WA005	8	
90866	6	
95286	2	

*14/3/03/20*

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
<b>Landing Gear</b> <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped. <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube				<b>General</b> <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio <input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions							
				<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge <input type="checkbox"/> Other							
				<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled							

# Picklist Print

Page 4

Tuesday, March 05, 2013 1:36:40 PM

Work Order ID: 98032

\*98032\*

Parent Item: D2221

\*D2221\*

Parent Item Name: 350 Basket Base

Start Date: 3/4/2013

Required Date: 4/9/2013

Start Qty: 1.00

Required Qty: 1.00

D3832-1

Manufactured No

100

Each

5.0000

1

1

\*\*

D87144 84,13.03.20

\*D3832-1\*

Mesh (Base)

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

WA	4	
----	---	--

96614	4	
-------	---	--

WA007	1	
-------	---	--

85951	1	
-------	---	--

D3833-1

Manufactured No

100

Each

14.0000

2

2

\*\*

B88 98096 → 2x

\*D3833-1\*

Mesh (Base End Face)

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

WA007	14	B 98096 →
-------	----	-----------

77521	4	(2)
-------	---	-----

81259	1	
-------	---	--

89208	1	
-------	---	--

92602	8	
-------	---	--

NCR: Yes / No


DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS						
			Rework	Skid-tube	Crosstube	Water Jet	Engineering					
			Scrap	Machining	Small Fab	Prod. Eng. Coor.	Quality					
			Use-as-is	Thermoforming	Finishing	Rec/Store/Packaging	Other					
			Work Order Update	Large Fab	Composite	Supplier						
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification	QC Inspector	
Doc/Data												
Equip/Tooling												
Operator												
Material												
Setup												
Other												
Process												
Supplier												
Training												
Unapproved												
FAULT CATEGORY												
Landing Gear	General											
	Bending	Bend	Grain	Ovalized	Pressure/Forced							
	Centre Not Concentric to O/S	BOM/Route	Hardware	Over/Under tolerance	Temperature/Cure							
	Cracks	Broken/Damaged	Inspection Incomplete	Part Incorrect	Weld							
	Crushed/Crimped.	Burrs	Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled							
	Cuffs	Contamination	Maintenance	Part Moved								
	Heat Treat	Countersink	Mislabeled	Positioned Wrong								
	Inspection Strip in Tube	Cut Too Short	Misread	Power Loss/Surge	Other							
	Ripples in Bend	Drill Holes	Offset									
	Torque Waves in Extrusion	Drawing	Out of Calibration									
	Turning Sequence	Finish	Out of Sequence									
	Wave/Twist in Tube	Folio	Outside Dimensions									

ITEM	QTY	P/N	DESCRIPTION
1	X	D2221	BASKET BASE ASSEMBLY (AS350)
2	1	D2221-1	RIB
3	2	D2221-5	RIB
4	1	D2221-7	RIB
5	2	D2232-3	BASKET HINGE
6	2	D2235-1	RIB
7	2	D2581	MOUNTING BRACKET
8	2	D3442-1	SHIM
9	2	D3825-041	RIB ASSY (BASKET END)
10	2	D3826-041	RIB/GUSSET ASSY
11	1	D3827-041	RIB ASSY (INBOARD)
12	2	D3833-1	MESH, BASE END FACE
13	1	D3832-1	MESH (BASE)



**D2221 BASKET BASE ASSEMBLY (AS350)**  
(MESH SHOWN LOCALLY FOR CLARITY)

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: POWDER COAT GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 42.00 lbs APPROX
- 8) MASK ALL HOLES PRIOR TO POWDER COATING

H	REVISED PARTS LIST AND ADDED "ITEM" COLUMN TO PARTS LIST (ZN D3-1); REVISED SECTIONS A-A, B-B AND C-C (ZN C6-3, C2-3 AND A6-3); REVISED DETAIL D (ZN B7-4); ADDED DETAIL E (ZN A6-4); ADDED SECTION F-F (ZN B2-4); ADDED DWG DETAILS FOR D2221-1/5-7 (SHEET 1); TOLERANCES IN 2 DEC PLACES (ZN D8-3 AND ZN B4-3). DRAFTING: D2221-1/5-7, D3826-041 REPLACES D2235-1/2, D3826-041, D3827-041, D3832-1, D3833-1. REASON: SATISFY "LEAN MANUFACTURING" PROGRAM.	MB	08.09.18
G	MATERIAL FOR 1, -3, -5 & -7 WAS 0.060 WALL. TOLERANCE FOR 96.00 DIM WAS 0.01 AND 56.00 DIM WAS REF (ZN B4-3). 19.62 DIM WAS "H" DIMENSION. DIM IS NOW "REF" (ZN B4-3). NOTE 5 TRANSFERRED FROM SHT 1 TO SHT 2. SHT 2 MESH MATERIAL UPDATED; DRAWING TRANSFERRED TO "B" FORMAT	AJS	08.06.16
F	ADD SHIM UNDER HINGE; ADD HOLES FOR SPLIT LID BASKET	PH	05.06.07
E	CHANGE HINGE	CP	01.04.19
D	CHANGE LATCH	BW	96.06.21
C	SEPARATE BASKET AND LID	KH	95.11.21
REV.	DESCRIPTION	BY	DATE
DESIGN	BW	<b>DART AEROSPACE LTD</b> HAWKESBURY, ONTARIO, CANADA	
DRAWN		DRAWING NO. <i>1335</i> REV. H D2221 SHEET 1 OF 5	
CHECKED		TITLE SCALE	
MFG. APPR.		BASKET BASE ASSEMBLY (350) NTS	
APPROVED		DATE 08.09.18	
DE APPR.		COPYRIGHT © 1994 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	


NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS						
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>					
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>					
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>					
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>						
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification	QC Inspector	
Doc/Data												
Equip/Tooling												
Operator												
Material												
Setup												
Other												
Process												
Supplier												
Training												
Unapproved												
FAULT CATEGORY												
Landing Gear	Bending Centre Not Concentric to O/S Cracks Crushed/Crimped. Cuffs Heat Treat Inspection Strip in Tube Ripples in Bend Torque Waves in Extrusion Turning Sequence Wave/Twist in Tube			General								
				Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>					
				BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>					
				Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>					
				Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>					
				Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>						
				Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>						
				Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>					
				Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>							
				Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>							
				Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>							
				Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>							




NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION		AGAINST DEPARTMENT/PROCESS												
			Rework Scrap Use-as-is Work Order Update	Skid-tube Machining Thermoforming Large Fab	Crosstube Small Fab Finishing Composite	Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier	Engineering Quality Other										
Root Cause		Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector						
Doc/Data																	
Equip/Tooling																	
Operator																	
Material																	
Setup																	
Other																	
Process																	
Supplier																	
Training																	
Unapproved																	
FAULT CATEGORY																	
Landing Gear			General														
<input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped. <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube			<input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio <input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions									<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge <input type="checkbox"/> Other			<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled		



RELEASED  
05/11/2010

DESIGN	EW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
DRAWN	3			
CHECKED	2/25	DRAWING NO.	REV. H	
MFG. APPR.	M	D2221	SHEET 3 OF 5	
APPROVED	1/1	TITLE	SCALE	
DE APPR.	H	BASKET BASE ASSEMBLY (350) NTS		
DATE	08.09.18	COPYRIGHT © 1984 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT THE WRITTEN CONSENT OF DART AEROSPACE LTD.		


NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear	General										
	Bending <input type="checkbox"/>	Bend <input type="checkbox"/>		Grain <input type="checkbox"/>							
	Centre Not Concentric to O/S <input type="checkbox"/>	BOM/Route <input type="checkbox"/>		Hardware <input type="checkbox"/>							
	Cracks <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>		Inspection Incomplete <input type="checkbox"/>							
	Crushed/Crimped. <input type="checkbox"/>	Burrs <input type="checkbox"/>		Instructions Incomplete/Unclear <input type="checkbox"/>							
	Cuffs <input type="checkbox"/>	Contamination <input type="checkbox"/>		Maintenance <input type="checkbox"/>							
	Heat Treat <input type="checkbox"/>	Countersink <input type="checkbox"/>		Mislabeled <input type="checkbox"/>							
	Inspection Strip in Tube <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>		Misread <input type="checkbox"/>							
	Ripples in Bend <input type="checkbox"/>	Drill Holes <input type="checkbox"/>		Offset <input type="checkbox"/>							
	Torque Waves in Extrusion <input type="checkbox"/>	Drawing <input type="checkbox"/>		Out of Calibration <input type="checkbox"/>							
	Turning Sequence <input type="checkbox"/>	Finish <input type="checkbox"/>		Out of Sequence <input type="checkbox"/>							
	Wave/Twist in Tube <input type="checkbox"/>	Folio <input type="checkbox"/>		Outside Dimensions <input type="checkbox"/>							



NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____	DISPOSITION			AGAINST DEPARTMENT/PROCESS														
Part No. _____	Rework	Scrap	Use-as-is	Skid-tube	Machining	Thermoforming	Large Fab	Crosstube	Small Fab	Finishing	Composite	Water Jet	Prod. Eng. Coor.	Rec/Store/Packaging	Supplier	Engineering	Quality	Other
NCR No. _____	Work Order Update																	
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification		QC Inspector						
Doc/Data																		
Equip/Tooling																		
Operator																		
Material																		
Setup																		
Other																		
Process																		
Supplier																		
Training																		
Unapproved																		
FAULT CATEGORY																		
Landing Gear				General														
				Bending	Bend	Grain	Ovalized	Pressure/Forced										
				Centre Not Concentric to O/S	BOM/Route	Hardware	Over/Under tolerance	Temperature/Cure										
				Cracks	Broken/Damaged	Inspection Incomplete	Part Incorrect	Weld										
				Crushed/Crimped.	Burrs	Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled										
				Cuffs	Contamination	Maintenance	Part Moved											
				Heat Treat	Countersink	Mislabeled	Positioned Wrong											
				Inspection Strip in Tube	Cut Too Short	Misread	Power Loss/Surge	Other										
				Ripples in Bend	Drill Holes	Offset												
				Torque Waves in Extrusion	Drawing	Out of Calibration												
				Turning Sequence	Finish	Out of Sequence												
				Wave/Twist in Tube	Folio	Outside Dimensions												

8 7 6 5 4 3 2 1

D

D



0.75 X 45° CHAMFER  
2 PL

H D2221-1 RIB

98632

C

C



H D2221-5-7 RIB

B

B

A

A

## NOTES:

- 1) MATERIAL: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.75 X 0.75 X 0.065 WALL  
REF. DART SPEC. M304TS0.750W0.065
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 8) WEIGHT: D2221-1 = 4.57 lbs; D2221-5 = 0.90 lbs; D2221-7 = 2.65 = lbs

DESIGN	BW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN		DRAWING NO. D2221
CHECKED	<i>AS</i>	REV. H
MFG. APPR.	<i>NO</i>	SHEET 5 OF 5
APPROVED	<i>W</i>	SCALE
DE APPR.	<i>W</i>	TITLE
DATE	08.09.18	BASKET BASE ASSEMBLY (350) NTS

COPYRIGHT © 1994 BY DART AEROSPACE LTD  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE LTD

8

7

6

5

4

3

2

1

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

## WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			DISPOSITION			AGAINST DEPARTMENT/PROCESS					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>				
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>				
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>				
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear				General							
				Bending <input type="checkbox"/>	Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>			
				Centre Not Concentric to O/S <input type="checkbox"/>	BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>			
				Cracks <input type="checkbox"/>	Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>			
				Crushed/Crimped. <input type="checkbox"/>	Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>			
				Cuffs <input type="checkbox"/>	Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>				
				Heat Treat <input type="checkbox"/>	Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>				
				Inspection Strip in Tube <input type="checkbox"/>	Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>			
				Ripples in Bend <input type="checkbox"/>	Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>					
				Torque Waves in Extrusion <input type="checkbox"/>	Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>					
				Turning Sequence <input type="checkbox"/>	Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>					
				Wave/Twist in Tube <input type="checkbox"/>	Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>					